	Type	L#	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	0	Chen-BoSu.in. and @pd>20030629	USPAT; US-PGPUB; EPO; JPO	2003/12/29 15:19			0
2	BRS	L3	1	Chen-Bo-Su.in. and @pd>20030629	USPAT; US-PGPUB; EPO; JPO	2003/12/29 15:20			0
3	BRS	L4	4	(Chen-B.in. and light) and @pd>20030629	DERWENT	2003/12/29 15:26			0
4	BRS	L5	8	((torque twist$3 rotat$3) near5 (optical$2 light illumination laser LED VCSEL)) near5 (code$1 coding encode$1 barcode mark$3) near5 (reflect$3 transmitted transmissive) and @pd>20030629	USPAT; US-PGPUB	2003/12/29 15:27			0
5	BRS	L6	3	((torque twist$3 rotat$3) near5 (optical$2 light illumination laser LED VCSEL)) near5 (code$1 coding encode$1 barcode mark$3) near5 (reflect$3 transmissive) and @pd>20030629	EPO; JPO; DERWENT; IBM_TDB	2003/12/29 15:33			0
6	BRS	L7	1	(torque twist$3 rotat$3) near5 (optical$2 light illumination laser LED VCSEL) near5 moire and @pd>20030629	USPAT; US-PGPUB	2003/12/29 16:43			0
7	BRS	L8	2	(torque twist$3 rotat$3) near5 ((vertical adj cavity) VCSEL) and @pd>20030629	USPAT; US-PGPUB	2003/12/29 16:47			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
8	BRS	L9	291	(73/862.321.ccls. 235/454.ccls. 235/494.ccls. 235/470.ccls. 235/462.01.ccls. 235/462.13.ccls. 356/395.ccls. 356/616.ccls. 356/618.ccls. 356/35.5.ccls. 250/231.16.ccls. 250/231.13.ccls. 250/231.1.ccls. 702/43.ccls. 702/42.ccls. 702/41.ccls. 73/800.ccls. 73/862.327.ccls. 73/862.326.ccls. 73/862.325.ccls. 73/862.324.ccls.) and @pd>20030629	USPAT; US-PGPUB	2003/12/29 15:43			0
9	BRS	L10	16	(torque twist$3 rotat$3) near5 (optical$2 light illumination laser LED VCSEL) near5 moire	EPO; JPO; DERWENT; IBM_TDB	2003/12/29 16:43			0
10	BRS	L11	1	(torque twist$3 rotat$3) near5 ((vertical adj cavity) VCSEL)	EPO; JPO; DERWENT; IBM_TDB	2003/12/29 16:47			0